













### 3 ACCEPTABLE METHODS TO REMOVE EXCESS THREAD

Hacksaw




Fig. 10a

Grinder




Fig. 10b




Fig 10c